



Your kind of place.

Parker and Pine Filing 1 Probationary Storm Punchlist
2/11/22

1. Replace all non-standard manhole covers on both inlets and manholes with the Town's standard manhole cover.
2. Clean all pond structures of sediment and debris. Will reinspect once cleaned.
3. MH B01: Add 2 steps.
4. Inlet A04: Epoxy grout crack in pipe invert and the first joint towards MH A03.
5. Inlet C00: Epoxy grout all penetrations flush with inlet wall.
6. Inlet C01: Epoxy grout pipe penetration to Inlet C00 flush with inlet wall.
7. Inlet A02: Patch chipped inlet deck. Epoxy grout the cracks in the pipe penetration at the structure, the first joint, and the cracks noted in the second joint towards toward MH B02. Coordinate with Civil Inspector on potential resolutions to address the raised inlet deck which presents a potential tripping hazard.
8. Inlet B03: Epoxy grout the southern pipe penetration. Repair steps broken by the southern pipe penetration.
9. MH B04: Add steps in the riser rings. Will reinspect once appropriate access is provided.
10. Inlet B05: Epoxy grout all penetrations flush with inlet wall.
11. MH B06: Add steps. Center cover ring. Provide concrete collar around cover ring.
12. MH B07: Replace broken riser rings. Center cover ring. Provide concrete collar around cover ring.
13. Inlet B08: Epoxy grout all penetrations flush with inlet wall. Provide a concrete collar for the crack in the pipe to MH B08.1.