

- Three-phase pad mount equipment with cooling fins shall have a clear working space minimum of one foot-6 inches (1'-6") on the sides and 2 feet-6 inches (2'-6") on the rear of the equipment, and 10 feet (10'-0") in front of the equipment.

PLAN VIEW OF PAD MOUNTED THREE-PHASE
TRANSFORMER CLEAR WORKING SPACE

